

Figure 1




Figure 2a




Figure 2b

Mobile terminals being
compensated

120 ₅₁ -M	120 ₅₂ -M	120 ₅₃ -M
120 ₅₂ -M		
120 ₅₃ -M	120 ₅₃ -M	

Mobile terminals listed below the header are
phantoms to the mobile terminals in the header.

Figure 3




Figure 4a




Figure 5




Figure 6

1005630-10501




Figure 7




Figure 8




Figure 9

Mobile terminals
being compensated

220 ₅₁ -DM	220 ₅₂ -DM	220 ₈₃ -DM	220 ₉₄ -DM	220 ₉₅ -DM	220 ₅₆ -DM
220 ₅₂ -DM					
220 ₈₃ -DM	220 ₈₃ -DM				
220 ₉₄ -DM	220 ₉₄ -DM	220 ₉₄ -DM			
220 ₉₅ -DM	220 ₉₅ -DM	220 ₉₅ -DM	220 ₉₅ -DM		
220 ₅₆ -DM	220 ₅₆ -DM	220 ₅₆ -DM	220 ₅₆ -DM	220 ₅₆ -DM	

Mobile terminals listed below the header are
phantoms to the mobile terminals in the header.

Figure 10

